

MRB Workshop Services  
Maryland House  
23 Rutland Street  
Swinton  
Manchester  
M27 6AU  
Tel: 0161 793 4040  
Fax: 0161 822 0070



Total project  
management.....  
Total workshop  
solution.....

## Thorough Examination & Load Test of Lifting Equipment

This Report complies with the requirements of the lifting operations and Lifting Equipment Regulations 1998

<b>Customer details:</b> Preston Scania Preston		<b>Site Address:</b>	<b>Report No</b> MRB2019-09-2695	<b>Date Of Examination</b> 17/09/2019
				Page 7
<b>Job no:</b>	<b>Prev Exam Date:</b>	<b>Next Exam Date: 17/09/2020</b>		
<b>Description and Identification of the Equipment Examined:-</b>				
<b>I.D No:</b>	090303-4	<b>Description:</b> Column lift	<b>RV Activated:</b> No	
<b>Serial No:</b>		<b>Manufacture:</b> Totalkare		
<b>Mfg. Date:</b>	N/K	<b>Location:</b>	<b>S.W.L:</b> 6.5T	
<b>Type Of Examination/Test Carried Out</b> Thorough examination & load test		<b>Examination Results/Equipment Status</b> PASS		<b>Safe For use:</b> YES
<b>(A) DEFECTS</b> - In need of attention to prevent immediate failure & details of action required to		<b>(B) DEFECTS</b> - To be kept under observation. Date when defects must be rectified by and parts required		
Defects: None Action Required:		Defects: None Parts Required: Date to be Rectified:		
<b>Particulars of any tests carried out as part of the Examination</b>			<b>Additional comments made as part of this Examination:</b>	
<b>Asset Code:</b> <b>Equipment Type:</b> <b>Manufacturer:</b> <b>UKAS Lab no:</b> <b>Last Examination on:</b> 12/04/2019 <b>Next Examination:</b> 12/04/2020				
<b>Examination carried out by</b>		<b>Examiner Details</b>		<b>Signatory for MRB Workshop Services</b>
MRB Workshop services Ltd Maryland House 23 Rutland street Swinton Manchester, M27 6AU		<b>Name:</b> B.Radford <b>Position:</b> Engineer  <b>Signature</b>		<b>Name</b> M. Bates <b>Date</b> 14/10/2019  <b>Signature</b>

