

MRB Workshop Services
 Maryland House
 23 Rutland Street
 Swinton
 Manchester
 M27 6AU
 Tel: 0161 793 4040
 Fax: 0161 822 0070



Total project
 management.....
 Total workshop
 solution.....

Thorough Examination & Load Test of Lifting Equipment

This Report complies with the requirements of the lifting operations and Lifting Equipment Regulations 1998

Customer details: Haydock Commercials Coop St Helens		Site Address:	Report No MRB2019-09-2764	Date Of Examination 26/09/2019
				Page 8
Job no:	Prev Exam Date:	Next Exam Date: 26/09/2020		
Description and Identification of the Equipment Examined:-				
I.D No:	02366A/B	Description: Pit jack	RV Activated: No	
Serial No:		Manufacture: Autolift		
Mfg. Date:	N/K	Location:	S.W.L: 10T each ram	
Type Of Examination/Test Carried Out Thorough examination & load test		Examination Results/Equipment Status Pass		Safe For use: Yes
(A) DEFECTS - In need of attention to prevent immediate failure & details of action required to		(B) DEFECTS - To be kept under observation. Date when defects must be rectified by and parts required		
Defects: None Action Required:		Defects: None Parts Required: Date to be Rectified:		
Particulars of any tests carried out as part of the Examination			Additional comments made as part of this Examination:	
Asset Code: Equipment Type: Manufacturer: UKAS Lab no: Last Examination on: 12/04/2019 Next Examination: 12/04/2020				
Examination carried out by	Examiner Details		Signatory for MRB Workshop Services	
MRB Workshop services Ltd Maryland House 23 Rutland street Swinton Manchester, M27 6AU	Name: B.Radford Position: Engineer Signature	Name M. Bates Date 28/10/2019 Signature		

