

MRB Workshop Services
 Maryland House
 23 Rutland Street
 Swinton
 Manchester
 M27 6AU
 Tel: 0161 793 4040
 Fax: 0161 822 0070



Total project management.....
 Total workshop solution.....

Thorough Examination & Load Test of Lifting Equipment

This Report complies with the requirements of the lifting operations and Lifting Equipment Regulations 1998

Customer details: Haydock Commercials Deeside Trucks Mold		Site Address:	Report No MRB2019-10-2845	Date Of Examination 07/10/2019
				Page 13
Job no:	Prev Exam Date:	Next Exam Date: 07/10/2020		
Description and Identification of the Equipment Examined:-				
I.D No:	PJ6A/B	Description: Pit Jack c/w 2 rams	RV Activated: No	
Serial No:		Manufacture: ABCO		
Mfg. Date:	N/K	Location:	S.W.L: 10T EA Ram	
Type Of Examination/Test Carried Out Thorough examination & load test		Examination Results/Equipment Status Pass		Safe For use: Yes
(A) DEFECTS - In need of attention to prevent immediate failure & details of action required to Pump Unit brackets bending away Defects: None Action Required:		(B) DEFECTS - To be kept under observation. Date when defects must be rectified by and parts required Top up oil level 2 L & bleed. Free off ram A locking collar. Silencer missing Defects: None Parts Required: Date to be Rectified:		
Particulars of any tests carried out as part of the Examination			Additional comments made as part of this Examination:	
Asset Code: LE304 Equipment Type: 10 T load cell Manufacturer: D&J Fabrications UKAS Lab no: N/A Last Examination on: 12/04/2019 Next Examination: 12/04/2020				
Examination carried out by MRB Workshop services Ltd Maryland House 23 Rutland street Swinton Manchester, M27 6AU		Examiner Details Name: B.Radford Position: Engineer Signature		Signatory for MRB Workshop Services Name M. Bates Date 08/11/2019 Signature

