MRB Workshop Services
Maryland House
23 Rutland Street
Swinton
Manchester
M27 6AU
Tel: 0161 793 4040
Fax: 0161 822 0070

Swinton

Manchester, M27 6AU



## **Thorough Examination & Load Test of Lifting Equipment**

This Report complies with the requirements of the lifting operations and Lifting Equipment Regulations 1998

Customer details: Haydock Commercials Deeside Trucks Mold  Job no: Prev Exam Date:		Site Address	Site Address:		0	Date Of Examination	
					9-10-2864	07/10/2019	
						Page 32	
		e:	Next Exam Date		2020		
Description and Identification of the Equipme		-				DVA-12 and NO	
I.D No: AS2			Description: High axle stand		RV Activated: NO		
Serial No:			Manufacture: Somers		6 14 1 7 5		
Mfg. Date: N/K		Location:	Location: S.W.L: 7.5T				
Type Of Examination/Test Carried Out Thorough examination & load test		Examination Pass	Examination Results/Equipment Status Pass			Safe For use: Yes	
(A) DEFECTS - In n	eed of attention to pre	vent	(B) DEFECTS - To be kept under observation. Date when defects must be			ı. Date when defects must be	
immediate failure	& details of action requ	uired to	rectified by and	parts require	d		
Defects: None			Defects: None				
Action Required:			Parts Required:				
			Date to be Rec	tified:			
Particulars of any tests carried out as part of the Examination			on	Additiona	l comments m	ade as part of this Examination:	
Asset Code: MRI							
Equipment Type							
Manufacturer: D							
UKAS Lab no: 04							
	n on: 02/04/2019						
Next Examinatio	n: U2/U4/2U2U					_	
Examination carrie	xamination carried out by Examiner Deta		tails	Signatory	for MRB Work	shop Services	
MRB Workshop	services Ltd	Name:	B.Radford	Name	M. Bates		
Maryland House 23 Rutland stree		Position:	Engineer	Date	08/11/202	19	

Signature

Signature

