

MRB Workshop Services
Maryland House
23 Rutland Street
Swinton
Manchester
M27 6AU
Tel: 0161 793 4040
Fax: 0161 822 0070



Total project
management.....
Total workshop
solution.....

Thorough Examination & Load Test of Lifting Equipment

This Report complies with the requirements of the lifting operations and Lifting Equipment Regulations 1998

Customer details: North West Trucks Huyton		Site Address:	Report No MRB2019-10-2924	Date Of Examination 01/10/2019
				Page 12
Job no:	Prev Exam Date:	Next Exam Date: 01/10/2020		
Description and Identification of the Equipment Examined:-				
I.D No:	APL2	Description: Bow Shackle	RV Activated: No	
Serial No:		Manufacture: Not known		
Mfg. Date:	N/K	Location:	S.W.L: 3.25 T	
Type Of Examination/Test Carried Out Thorough examination & load test		Examination Results/Equipment Status PASS		Safe For use: Yes
(A) DEFECTS - In need of attention to prevent immediate failure & details of action required to		(B) DEFECTS - To be kept under observation. Date when defects must be rectified by and parts required		
Defects: None Action Required:		Defects: None Parts Required: Date to be Rectified:		
Particulars of any tests carried out as part of the Examination			Additional comments made as part of this Examination: Grinding mark on body	
Asset Code: Equipment Type: Manufacturer: UKAS Lab no: N/A Last Examination on: 12/04/2019 Next Examination: 12/04/2020				
Examination carried out by MRB Workshop services Ltd Maryland House 23 Rutland street Swinton Manchester, M27 6AU		Examiner Details Name: B.Radford Position: Engineer Signature		Signatory for MRB Workshop Services Name M. Bates Date 18/11/2019 Signature

