

MRB Workshop Services  
 Maryland House  
 23 Rutland Street  
 Swinton  
 Manchester  
 M27 6AU  
 Tel: 0161 793 4040  
 Fax: 0161 822 0070



Total project management.....  
 Total workshop solution.....

## Thorough Examination & Load Test of Lifting Equipment

This Report complies with the requirements of the lifting operations and Lifting Equipment Regulations 1998

<b>Customer details:</b> Halton Council Widnes		<b>Site Address:</b>	<b>Report No</b> MRB2019-10-2982	<b>Date Of Examination</b> 11/10/2019
				Page 10
<b>Job no:</b>	<b>Prev Exam Date:</b>	<b>Next Exam Date: 11/10/2020</b>		
<b>Description and Identification of the Equipment Examined:-</b>				
<b>I.D No:</b>	NO2	<b>Description:</b> Ladder / platform	<b>RV Activated:</b> No	
<b>Serial No:</b>		<b>Manufacture:</b> Not known		
<b>Mfg. Date:</b>	N/K	<b>Location:</b>	<b>S.W.L:</b> 300 kgs	
<b>Type Of Examination/Test Carried Out</b> Thorough examination & load test		<b>Examination Results/Equipment Status</b> pass	<b>Safe For use:</b> yes	
<b>(A) DEFECTS</b> - In need of attention to prevent immediate failure & details of action required to		<b>(B) DEFECTS</b> - To be kept under observation. Date when defects must be rectified by and parts required  7 tread + platform SWL applied  Platform slippery due to grease + debris build up Defects: None Parts Required: Date to be Rectified:		
<b>Action Required:</b>				
<b>Particulars of any tests carried out as part of the Examination</b>			<b>Additional comments made as part of this Examination:</b>	

<b>Examination carried out by</b> MRB Workshop services Ltd Maryland House 23 Rutland street Swinton Manchester, M27 6AU	<b>Examiner Details</b> Name: B.Radford Position: Engineer  Signature	<b>Signatory for MRB Workshop Services</b> Name M. Bates Date 18/11/2019  Signature
---	---	---

