MRB Workshop Services
Maryland House
23 Rutland Street
Swinton
Manchester
M27 6AU
Tel: 0161 793 4040
Fax: 0161 822 0070



Thorough Examination & Load Test of Lifting Equipment

This Report complies with the requirements of the lifting operations and Lifting Equipment Regulations 1998

| Customer details: Halton Council | | Site Address: | | Report No MRB2019-10-3008 | | Date Of Examination 11/10/2019 | | |
|--|-------------------------|---------------------------|---------------------------------|-------------------------------------|--|-----------------------------------|--------|--|
| | | | | | | | Widnes | |
| | | | | | | 36 | | |
| | | | | | | | | |
| Job no: | Prev Exam Date: | | Next Exam Dat | Pate: 11/10/2020 | | | | |
| Description and Identific | cation of the Equipm | ent Fxamined:- | | | | | | |
| I.D No: 19H/20560-1909 | | Description: Jacking Beam | | RV Activated: | | l: Yes | | |
| Serial No: | | Manufacturer: Majorlift | | | | | | |
| Mfg. Date: N/K | | Location: | | | S.W.L: 2 T | | | |
| | | • | | | I | | | |
| | | | | | | | | |
| Type Of Examination/Te | st Carried Out | Examination Res | tatus | | Safe For use: | | | |
| Thorough examination | | pass | | | | yes | | |
| (A) DEFECTS - In need of | attention to prevent | · (1 | B) DEFECTS - To b | e kept unde | r observation. | Date when defects must be | | |
| immediate failure & deta | ails of action required | d to r | rectified by and parts required | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | Defects: None | | | | | |
| Action Required: | | | Parts Required: | | | | | |
| Action Required: | | | · | | | | | |
| | | | Date to be Rectif | ied: | | | | |
| Particulars of any tests carried out as part of the Examinatio | | | | Additional | comments made as part of this Examination: | | | |
| | | | | | | | | |
| Asset Code: MRB001 | | | | | | | | |
| Equipment Type: 25 T | on Load Cell | | | | | | | |
| Manufacturer: D&J Fal | | | | | | | | |
| UKAS Lab no: N/A | | | | | | | | |
| Last Examination on: 1 | 12/04/2019 | | | | | | | |
| Next Examination: 12/ | | | | | | | | |
| , | | | | | | | | |
| | | | | | | | | |
| Examination carried out | by | Examiner Details | | Signatory for MRB Workshop Services | | | | |

| Examination carried out by | Examiner De | etails | Signatory for MRB Workshop Services | | |
|----------------------------|-------------|-----------|-------------------------------------|--|--|
| MRB Workshop services Ltd | Name: | B.Radford | Name M. Bates | | |
| Maryland House | Position: | Engineer | Date 18/11/2019 | | |
| 23 Rutland street | | | | | |
| Swinton | Signature | | Signature | | |
| Manchester, M27 6AU | | | | | |

