

MRB Workshop Services
Maryland House
23 Rutland Street
Swinton
Manchester
M27 6AU
Tel: 0161 793 4040
Fax: 0161 822 0070



Total project
management.....
Total workshop
solution.....

Thorough Examination & Load Test of Lifting Equipment

This Report complies with the requirements of the lifting operations and Lifting Equipment Regulations 1998

Customer details: Halton Council Widnes		Site Address:	Report No MRB2019-10-3010	Date Of Examination 11/10/2019
				Page 38
Job no:	Prev Exam Date:	Next Exam Date: 11/10/2020		
Description and Identification of the Equipment Examined:-				
I.D No:	HBC CB18	Description: Chain block	RV Activated: No	
Serial No:		Manufacturer: Hubblast		
Mfg. Date:	N/K	Location:	S.W.L: 1000 Kgs	
Type Of Examination/Test Carried Out <u>Thorough examination & load test</u>		Examination Results/Equipment Status pass		Safe For use: yes
(A) DEFECTS - In need of attention to prevent immediate failure & details of action required to		(B) DEFECTS - To be kept under observation. Date when defects must be rectified by and parts required		
Action Required:		Defects: None Parts Required: Date to be Rectified:		
Particulars of any tests carried out as part of the Examination			Additional comments made as part of this Examination:	
Asset Code: 22014 Equipment Type: 12T beam and load cell Manufacturer: D&J Fabrications UKAS Lab no: N/A Last Examination on: 12/04/2019 Next Examination: 12/04/2020				

Examination carried out by MRB Workshop services Ltd Maryland House 23 Rutland street Swinton Manchester, M27 6AU	Examiner Details Name: B.Radford Position: Engineer Signature	Signatory for MRB Workshop Services Name M. Bates Date 18/11/2019 Signature
---	---	---

