MRB Workshop Services
Maryland House
23 Rutland Street
Swinton
Manchester
M27 6AU
Tel: 0161 793 4040
Fax: 0161 822 0070



## **Thorough Examination & Load Test of Lifting Equipment**

This Report complies with the requirements of the lifting operations and Lifting Equipment Regulations 1998

Customer details:		Site Address:		Report No		Date Of Examination				
Sefton Council				MRB2019-11-3134		12/11/2019				
Liverpool						Page				
						41				
Job no:	Prev Exam Date:	Next Exam D		te: 12/11/2020						
					-					
Description and Identification of the Equipment Examined:-										
I.D No:	VS4	Description: Axlo	e stand RV Activated		: No					
Serial No:		Manufacturer: Melco								
Mfg. Date: N/K Location:		Location:	S.W.L: 6 To							
Type Of Examination/Test Carried Out		Examination Results/Equipment Sta				Safe For use:				
Thorough examination & load test  (A) DEFECTS - In need of attention to prevent		Pass To be kept up		a kant unda	observation [	Yes				
	·		(B) DEFECTS - To be kept under observation. Date when defects must be							
immediate failure & details of action required		to rectified by and parts required								
		Defects: None								
Action Required:		Parts Required:								
		Date to be Rectified:								
Particulars of any tests carried out as part of the Examination			n Additional comments made as part of this Examination:							
, ,				,						
		Minor elongated of 2 holes on crutch								
Asset Code: MRB001				•						
Equipment Type: 25 T	on Load Cell									
Manufacturer: D&J Fabrications										
UKAS Lab no: N/A										
Last Examination on: 12/04/2019										
Next Examination: 12/04/2020										

Examination carried out by	Examiner Details		Signatory for MRB Workshop Services			
MRB Workshop services Ltd	Name:	B.Radford	Name	M. Bates		
Maryland House	Position:	Engineer	Date	27/11/2019		
23 Rutland street						
Swinton	Signature		Signature			
Manchester, M27 6AU						

