

MRB Workshop Services
 Maryland House
 23 Rutland Street
 Swinton
 Manchester
 M27 6AU
 Tel: 0161 793 4040
 Fax: 0161 822 0070



Total project
 management.....
 Total workshop
 solution.....

Thorough Examination & Load Test of Lifting Equipment

This Report complies with the requirements of the lifting operations and Lifting Equipment Regulations 1998

Customer details: Hyndburn Council Accrington		Site Address:	Report No MRB2019-10-3072	Date Of Examination 06/11/2019
				Page 42
Job no:	Prev Exam Date:	Next Exam Date: 06/11/2020		
Description and Identification of the Equipment Examined:-				
I.D No:	GD5795	Description: Chain block	RV Activated: Yes	
Serial No:		Manufacturer: Morris		
Mfg. Date:	N/K	Location:	S.W.L: 1 T	
Type Of Examination/Test Carried Out Thorough examination & load test		Examination Results/Equipment Status Pass		Safe For use: Yes
(A) DEFECTS - In need of attention to prevent immediate failure & details of action required to		(B) DEFECTS - To be kept under observation. Date when defects must be rectified by and parts required		
Action Required:		Defects: None Parts Required: Date to be Rectified:		
Particulars of any tests carried out as part of the Examination			Additional comments made as part of this Examination:	

Examination carried out by MRB Workshop services Ltd Maryland House 23 Rutland street Swinton Manchester, M27 6AU	Examiner Details Name: B.Radford Position: Engineer Signature	Signatory for MRB Workshop Services Name M. Bates Date 18/11/2019 Signature
---	---	---

